D

November 9, 2009 1:42:22 PM



Page 1

Item ID:

D2989-041

Accept

Setup Start

Stop



Revision ID:

Item Name:

Basket Lid Assembly

Start Date:

Required Date: 20/11/2009

09/11/2009

Start Qty: 1:00 Req'd Qty: 1.00



Cust Item ID: Customer:

Reference:

Approvals:

Process Plan:

Date: 59-11-01

Date:

A

0.00

Tooling: **SPC (Y/N):**

Date:

Date:

Start

Stop

Run



Sequence ID/ **Work Center ID**

Operation Description

Revision Nbr

Set Up/ **Run Hours** Draw Number

Plan Draw Rev.

Code

Accept Qty

Reject Qty

Reject Number

Insp. Stamp

Draw Nbr

D2989 Rev D

QC:

100

Large Fab Large Fab

Large Fab

Memo

0.00

1- assemble all ribs and both D2581 in DT9445 jig, weld as per dwg D2989

2- tack weld mesh on basket as per dwg D2989 using DT9445 jig ****cut cutouts with zip cut as per dwg D3832****

3- remove from jig and weld lable plate as per dwg D2989 A/R ER316 S.S. Rod Batch: 10921 3

110

QC9- Inspect visual per QSI004- Fusion Welds

0.00

Memo

0.00



Quality Control

Work Order ID 53600

D

November 9, 2009 1:42:22 PM



Page 2

Item ID:

D2989-041

Accept

Setup Start



Stop



Revision ID:

Item Name:

Basket Lid Assembly

Start Date:

09/11/2009

Start Qty: 1.00

OC:

Operation

Description

Required Date: 20/11/2009

Req'd Qty: 1.00



Date: _____

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: _____

Date:

Tooling:

Date:

Run

Stop

Start



Sequence ID/

Work Center ID

120

QC5- Inspect part completeness to step on W/O

Run Hours 0.00

SPC (Y/N):

Set Up/

0.00

Draw Number

Draw Rev.

Date:

Plan Code Accept Qty Oty

Reject Reject

Insp. Number

Stamp //


Quality Control

130



Powdercoat **Powder Coating** White Gloss(Ref:4.3.5.2) per QSI005 4.3-Steel

0.00



Memo

Memo

0.00

-1- Plug holes prior to powder coating

2-Powder Coat White (Ref. 4.3.5.2) D2989-041 as per QSI 005 4.3 & Dwg

D2989

M112148

1ST COAT:

START TIME:

OVEN TEMPERATURE: 4000 F

FINISH TIME: 11 15AM ********* 2nd coat if necessary **************

2ND COAT:

START TIME:

OVEN TEMPERATURE: 4

FINISH TIME:

Work Order ID 53600

D



Page 3

November 9, 2009 1:42:22 PM

Item ID:

D2989-041

Revision ID:

Item Name:

Basket Lid Assembly

Start Date:

09/11/2009

Start Qty: 1.00

Required Date: 20/11/2009

Accept



Setup Start



Stop

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Req'd Qty: 1.00

Date: _____

Wing Walk as per dwg QSI005 4.4 Batch MID 0,00

Date:

Tooling: SPC (Y/N):

0.00

Date: Date: Run

Start



Stop

Sequence ID/ **Work Center ID**

Operation Description Set Up/ **Run Hours**

Draw Number

MD09/11/17

Draw Plan Rev.

Code

Accept **Qty**

Reject **Qty**

Reject Number

Insp. Stamp

131

HandFinish Hand Finishing

Mask lid prior to spray paint black and wing walk as per dwg A/R Spray paint black batch: 2112473

BR 09-11-17

140

Quality Control

Memo

QC3- Inspect Part Finish

141

Packaging

Packaging

Identify as per dwg & Stock Location:_____

777 596 0.00

0.00

(cg/11/20 0

Memo

Work Order ID 53600



Page 4

November 9, 2009 1:42:22 PM

Item ID:

D2989-041

Accept



Setup Start



Stop

Revision ID:

D **Item Name:**

Basket Lid Assembly

Start Date:

09/11/2009

Start Oty: 1.00

Required Date: 20/11/2009

Req'd Qty: 1.00



Cust Item ID:

Customer:

Reference:

Approvals:

QC: _

Process Plan:

Date:

Date:

Tooling:

Date: Date: Start

Stop

Run



Sequence ID/

Work Center ID

Operation Description QC21- Final Inspection - Work Order Release Set Up/ **Run Hours**

SPC (Y/N):

Draw Number Draw Rev.

Accept Plan Code Qty

Reject Qty

Reject Number Stamp

Insp.

150

Memo

0.00

0.00

Quality Control

Bl 09-11-25

November 9, 2009 1:42:22 PM

Work Order ID: 53600

Parent Item:

D2989-041RevD

Parent Item Name: Basket Lid Assembly



Start Date: 09/11/2009

Required Date: 20/11/2009

Start Oty 1 00

Required Oty: 1.00

Comments:									Start Qty: 1.00)	Required Qty: 1.00
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Status Issued
D2221-1RevH	H	Manufactured	No			100	Each	18.0000	2.0000	SAD	09-11-19
				Warehou	<u>ise</u>	Loc	<u>Oty</u>	Loc Code			
				Loca	<u>tion</u>						
				Main Wa	rehouse						
				ST			1		_		
		•			48101		1 .		_		
				Main Wa	rehouse						,
				WA			17		_		a 1 .
	•				51872 53213		5 12		-	2 _y	Moduli
D2506RevF		Manufactured	No			100	Each	9.0000	1.0000	SAN	09-11-19

|--|

Label Plate

Warehouse	Loc Oty	Loc Code	
Location			
Main Warehouse			
ST	1		
44275	1		
Main Warehouse			,
WA	. 8		
52834	8		11 M09/11/11

November 9, 2009 1:42:22 PM

Page 2

Work Order ID: 53600

Parent Item:

D2989-041RevD

Parent Item Name: Basket Lid Assembly

Comments:



Start Date: 09/11/2009

Required Date: 20/11/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/	Replacement	Mfg/	Bin	Primary	Last	Route	Unit of	Qty on	Remaining	Qty	Date	Status
Item Name	Item ID	Purch	Item	Location	Location	Seq ID	Measure	Hand	Qty To Pick	Issued	Issued	
D2512-7RevE		Manufactured	No			100	Each	7.0000	1.0000	SAO	09-11-1	a

100

Rib

Warehouse	Loc Oty	Loc Code	
Location			
Main Warehouse			
ST	7		- Malilia
48666	3	_	Ix M09/11/11
53444	4		

D2581RevA1

Manufactured

48.0000 2.0000 Each

09-11-19

Mounting P	rookat	

Mounting Bracket

<u>Warehouse</u>	Loc Oty	Loc Code		
Location		<u></u>		
Main Warehouse				
ST	12			
46086	2			
48428	. 1			
51120	9			
Main Warehouse				
WA	36			. 1
50872	1			· IM
51745	35		જી 🗴	1 1 09

November 9, 2009 1:42:22 PM

Work Order ID: 53600

Parent Item:

D2989-041RevD

Parent Item Name: Basket Lid Assembly

Comments:



Start Date: 09/11/2009

Required Date: 20/11/2009

Page 3

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2989-13RevD		Manufactured	No			100	Each	6.0000	2.0000			
										30	09-11-1	9

Rib

Warehouse	Loc	c Oty	Loc Code		
Location					
Main Warehouse					
WA		6			
51864		2			<i>lM</i> i i
53128		4			ax Moglin
	100	Each	7.0000	2.0000	
					SAD 09-11-19

Manufactured No

Rib

D2989-19RevD

Warehouse Location	Loc Oty	Loc Code	
Main Warehouse			
ST	1		
44867	1		
Main Warehouse			
WA	6		
51338	2		
51874	4		21 M 09/11/11

November 9, 2009 1:42:22 PM

Page 4

Work Order ID: 53600

Parent Item:

D2989-041RevD

Parent Item Name: Basket Lid Assembly

Manufactured

No





Start Date: 09/11/2009

Required Date: 20/11/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3832-3RevA		Manufactured	No	•		100	Each	3.0000	1.0000			
										SAD	09-11-19	•

Mesh (Lid)

<u>Warehouse</u>	Loc	<u>Oty</u>	Loc Code				
Location							
Main Warehouse							
ST		3					
51865		3					
	100	Each	13.0000	2.0000			



Mesh (Lid End)

D3833-3RevA

Warehouse Location	Loc Otv	Loc Code
Main Warehouse		
ST	13	
46308	1	
53136	12	

Page 5

November 9, 2009 1:42:22 PM

Work Order ID: 53600

Parent Item:

D2989-041RevD

Parent Item Name: Basket Lid Assembly

Manufactured

No

Comments:



Start Date: 09/11/2009

Required Date: 20/11/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3836-041RevA		Manufactured	No			100	Each	3.0000	1.0000			
										SAN	60-11-19	

Rib Assembly (Basket Lid, LH)

Warehouse	Loc	Oty	Loc Code		
Location					
Main Warehouse					
ST		1			
51336		1			
Main Warehouse					
WA		2			-
53129		2			<u> </u>
	100	Each	5.0000	1.0000 	α

Rib Assembly (Basket Lid, RH)

D3836-042RevA

Warehouse	Loc Oty	Loc Code	
Location			
Main Warehouse			
ST	3		
51337	2		
53436	1		
Main Warehouse			
WA	2		-
53130	2		
53612			١×

53612

November 9, 2009 1:42:22 PM

Page 6

Work Order ID: 53600

Parent Item:

D2989-041RevD

Parent Item Name: Basket Lid Assembly

Manufactured No

Comments:



Start Date: 09/11/2009

Required Date: 20/11/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3852-041RevA		Manufactured	No			100	Each	3:0000	1.0000			
										SAN	Off	19

Rib Assembly

D3852-042RevA

Rib Assembly

Warehouse	Loc	Oty	Loc Code		
Location					
Main Warehouse					
ST		. 3			
51333		1			
53127		2			
	100	Each	3.0000	1.0	

<u>Warehouse</u>	Loc Oty	Loc Code
Location		
Main Warehouse		
ST	3	
51332	1	
53126	2	

IX Monthly

